



SERVO\_1  
SERVO\_2  
SERVO\_3  
SERVO\_4  
PWR\_IN

SCI

C1

RS232

U1

RX\_IN

HC11\_OUT